

Digital Service Report

Vehicle info

Vehicle	GLC 300 e 4MATIC
First reg. date	11.03.2021
FIN	W1N2533531F940xxx

Next Service	03.2025
	50204 km

(Please note the additional information in your vehicle (owner's manual, service booklet and service interval indicator) on the performance of the next service)

Service report 3

Mercedes-Benz	Veho Bil Sverige AB	Date	28.03.2024
	Smista Allé 42	Rep.-order-no.	9388850
	Segeltorp	Mileage	25204 km

Performed services

Service	Service A
Workshop code	3508
Remaining time	30 Days
Remaining distance	14300 km

Oil quality/viscosity

Description	Engine oil
Oil quality	229.5
Viscosity	

Replaced / renewed

Perform Service A with Plus package	<input checked="" type="checkbox"/>
-------------------------------------	-------------------------------------

Extra work for: Service: Replace air filter element	<input checked="" type="checkbox"/>
---	-------------------------------------

Extra work for: Service: Replace spark plugs	<input checked="" type="checkbox"/>
--	-------------------------------------

Until next service

Mercedes-Benz Mobilo	<input checked="" type="checkbox"/>
----------------------	-------------------------------------

Warr. against rusting through	<input checked="" type="checkbox"/>
-------------------------------	-------------------------------------

Service-intervals in accordance with Mercedes-Benz AG specification

Complied with	<input checked="" type="checkbox"/>
---------------	-------------------------------------

Additional operations performed

Accomplished	<input checked="" type="checkbox"/>
--------------	-------------------------------------

Service report 2

Mercedes-Benz

Veho Bil Sverige AB
Smista Allé 42
Segeltorp

Date 28.04.2023
Rep.-order-no. 8654900
Mileage 14479 km

Performed services

Service Service B
Workshop code EOE
Remaining time -43 Days
Remaining distance 18800 km

Oil quality/viscosity

Description Engine oil
Oil quality
Viscosity

Replaced / renewed

Engine: oil and filter change ☒
Brake fluid replaced ☒

Until next service

Mercedes-Benz Mobilo ☒
Warr. against rusting through ☒

Service-intervals in accordance with Mercedes-Benz AG specification

Complied with ☒

Additional operations performed

Accomplished ☒

Service report 1

Mercedes-Benz

Veho Bil Sverige AB
Smista Allé 42
Segeltorp

Date 16.03.2022
Rep.-order-no. 7853910
Mileage 8289 km

Performed services

Service Service A
Workshop code 505
Remaining time -5 Days
Remaining distance 16711 km

Oil quality/viscosity

Description Engine oil
Oil quality 229.5
Viscosity 5W-40

Replaced / renewed

Dust filter replaced ☒
Engine: oil and filter change ☒

Until next service

Mercedes-Benz Mobilo ☒
Warr. against rusting through ☒

Service-intervals in accordance with Mercedes-Benz AG specification

Complied with ☒

Additional operations performed

Accomplished ☒
